


BUSHING CHART



For more information call 800-542-3088 or visit our web site at www.mckinneycorp.com

STYLES




PART #	FIGURE	MATERIAL	I.D.		LENGTH	FLANGE DIA.	FLANGE THCKNS	BORE	
			I	O				B	D
M-240	FIG. 3	4130	0.191	0.500	0.500			0.344	0.200
M-62-B	FIG. 1	4130	0.250	0.375	0.313				
M-62-BTI	FIG. 1	Titanium	0.250	0.375	0.313				
M-93	FIG. 1	4130	0.250	0.500	0.625				
M-29	FIG. 1	4130	0.272	0.438	1.375				
M-29-TI	FIG. 1	Titanium	0.272	0.438	1.375				
M-1-D	FIG. 1	4130	0.313	0.438	0.250				
M-148-F	FIG. 1	6061	0.313	0.875	0.250				
M-4273-B	FIG. 1	4130	0.313	0.625	0.500				
M-4262-D	FIG. 1	4130	0.313	0.438	1.500				
M-43-B	FIG. 1	4130	0.313	0.500	1.995				
M-43-A	FIG. 1	4130	0.313	0.500	2.495				
M-3211	FIG. 1	6061	0.344	0.600	1.000				
M-3210	FIG. 1	6061	0.344	0.550	2.563				
M-62	FIG. 1	4130	0.375	0.563	0.313				
M-4273-A	FIG. 1	4130	0.375	0.750	0.375				
M-236	FIG. 1	4130	0.375	0.750	0.470				
M-19-C	FIG. 1	6061	0.375	1.000	0.500				
M-232	FIG. 3	4130	0.375	0.750	0.585			0.625	0.440
M-291-A	FIG. 1	4130	0.375	0.750	0.925				
M-117	FIG. 1	4130	0.375	0.563	1.000				
M-19-B	FIG. 1	6061	0.375	1.000	1.000				
M-231	FIG. 1	4130	0.375	0.750	1.125				
M-230	FIG. 1	4130	0.375	0.563	1.250				
M-68	FIG. 1	4130	0.375	0.563	1.500				
M-68-TI	FIG. 1	Titanium	0.375	0.563	1.500				
M-68-B	FIG. 1	4130	0.375	0.563	1.855				
M-68-BTI	FIG. 1	Titanium	0.375	0.563	1.855				
M-97	FIG. 2	4130	0.375	0.563	2.000	0.875	0.250		
M-4784	FIG. 2	4130	0.375	0.750	2.125	1.000	0.250		
M-19-A	FIG. 3	6061	0.375	1.000	3.000				
M-11	FIG. 1	4130	0.384	0.500	1.000				
M-121-B	FIG. 1	4130	0.384	0.500	2.688				
M-4765-B	FIG. 1	4130	0.438	0.750	0.250				
M-4765-BT	FIG. 1	Titanium	0.438	0.750	0.250				
M-36	FIG. 1	4130	0.438	0.750	0.313				
M-266-B	FIG. 1	6061	0.438	0.750	0.400				
M-3723-B	FIG. 1	4130	0.438	0.650	0.750				
M-231-A	FIG. 1	4130	0.438	0.750	1.125				
M-233	FIG. 1	4130	0.438	0.750	1.375				
M-55	FIG. 2	4130	0.484	0.688	1.100	1.000	0.100		
M-42	FIG. 1	4130	0.500	0.688	0.500				
M-20	FIG. 1	4130	0.500	0.622	0.735				

BUSHING CHART



For more information call 800-542-3088 or visit our web site at www.mckinneycorp.com

STYLES



PART #	FIGURE	MATERIAL	I.D.		LENGTH	FLANGE DIA.		BORE	
			I	O		L	F	T	B
M-39	FIG. 1	4130	0.500	0.875	1.250				
M-68-A	FIG. 1	4130	0.500	0.750	1.500				
M-68-ATI	FIG. 1	Titanium	0.500	0.750	1.500				
M-15	FIG. 1	4130	0.500	0.750	1.540				
M-118	FIG. 1	4130	0.500	0.688	1.750				
M-38	FIG. 1	4130	0.500	0.688	1.875				
M-38-T	FIG. 1	Titanium	0.500	0.688	1.875				
M-4766-E	FIG. 1	4130	0.500	0.875	1.875				
M-14-T	FIG. 1	4130	0.527	0.625	1.750				
M-293-A	FIG. 1	6061	0.630	0.812	0.800				
M-101-A	FIG. 1	4130	0.709	0.875	0.875				
M-178	FIG. 1	6061	0.844	1.010	1.000	1.125	0.250		
M-2011	FIG. 1	4130	1.259	1.375	2.000				
M-63-C	FIG. 2	4130	#10-32	0.310	0.455	0.375	0.125		
M-90-C	FIG. 1	4130	#10-32	0.500	0.625				
M-179	FIG. 2	4130	#10-32	0.365	0.750			0.328	0.200
M-4766-D	FIG. 1	4130	1/2"-20	0.688	1.000				
M-4766-DT	FIG. 1	Titanium	1/2"-20	0.688	1.000				
M-63-B	FIG. 2	4130	1/4"-28	0.370	0.600	0.500	0.125		
M-63-A	FIG. 2	4130	5/16"-24	0.430	0.750	0.563	0.125		
M-120-A	FIG. 1	4130	5/16"-24	0.438	1.188				
M-120-ATI	FIG. 1	Titanium	5/16"-24	0.438	1.188				
SPL-404	FIG. 1	4130	7/16"-20	0.875	1.000				